

PATENT Cofe

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	n : m I
MANABU TAKEBAYASHI		:	Examiner: Twyler Lamb
Appln. No.: 09/897,032		:	Art Unit: 2622
Filed: July 3, 2001		:	
For:	IMAGE FORMING APPARATUS AND ITS CONTROL METHOD) :)	
U.S. Patent No.: 6,992,793 B2) : \	
Issued:	January 31, 2006) :	February 5, 2007

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION

UNDER AND 323

of Correction

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee

for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

ennifer A. Reda

Attorney for Patentees Registration No. 57,840

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801

Facsimile: (212) 218-2200

603036v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,992,793 B2

DATED

January 31, 2006

INVENTOR(S) :

MANABU TAKEBAYASHI

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 5

Line 53, "are formed" should read -- is formed--.

COLUMN 6

Line 52, "embedded." should read --embedded in the region B.--.

COLUMN 10

Line 11, "be appended" should read --to be appended--; and

Line 51, "video controller 3005" should read --video controller 300--.

COLUMN 13

Line 35, "user's" should read --the user's--; and

Line 46, "single" should read --single item of--.

COLUMN 14

Line 49, "append" should read --appends--;

Line 53, "differ" should read --differs--; and

Line 64, "include:" should read --includes:--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>US 6,992,793 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

603036v1

No. of add'l. copies @ 30¢ per page

FEB 1 2 2007

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,992,793 B2

DATED

January 31, 2006

INVENTOR(S) :

MANABU TAKEBAYASHI

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 15

Line 5, "include:" should read --includes:--; Line 12, "include:" should read --includes:--; Line 19, "include:" should read --includes:--; and Line 28, "include:" should read --includes:--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. US 6,992,793 B2

FEB 1 2 2007

Form PTO 1050 (Rev. 3-82)

603036v1